



## Department of Energy

ROCKY FLATS FIELD OFFICE  
P.O. BOX 928  
GOLDEN, COLORADO 80402-0928

MAR 09 1995

95-DOE-08209

Mr. Martin Hestmark  
U. S. Environmental Protection Agency, Region VIII  
ATTN: Rocky Flats Project Manager, 8HWM-RI  
999 18th Street, Suite 500, 8WM-C  
Denver, Colorado 80202-2405

Mr. Joe Schieffelin, Unit Leader  
Hazardous Waste Facilities  
Colorado Department of Public Health and Environment  
4300 Cherry Creek Drive South  
Denver, Colorado 80222-1530


Gentlemen:

Enclosed is the Quarterly Report for Operable Unit 1 (OU 1) Interim Measure/Interim Remedial Action (IM/IRA) for the period of October through December 1994 (Enclosure 1). The report includes an operational summary report for the quarter and validated data from the previous quarter for the ground water monitoring wells, the French Drain Sump, the Building 881 Footing Drain, and the ion exchange columns.

Also enclosed are additional copies of the previous Quarterly Report as was requested by G. Kleeman of your staff (Enclosure 2). The previous quarterly report was originally submitted to you by our December 14, 1994 letter (Ref: 94-DOE-12398).

Please contact Dave George at 966-5669 if you have any questions regarding this material.

Sincerely,

  
Steven W. Slaten  
IAG Project Coordinator  
Environmental Restoration

Enclosure

Hestmark & Schieffelin  
95-DOE-08209

2

MAR 09 1995

cc w/Enclosure:  
G. Kleeman, EPA  
C. Gilbreath, CDPHE

cc w/o Enclosure:  
C. Gesalman, EM-453, HQ  
J. Ciocco, EM-453, HQ  
F. Lockhart, ER, RFFO  
J. Wienand, ER, RFFO  
D. George, ER, RFFO  
T. Reeves, SAIC  
M. Rupert, EG&G  
R. Cirillo, EG&G